

## 'Na Aksa Gyilak' yoo School - Accessibility Plan

### Accessibility Barrier & Action Table

<b>Barrier Identified</b>	<b>Impact</b>	<b>Action to Remove Barrier</b>	<b>Timeline</b>	<b>Responsible</b>
Loose gravel (rock) and uneven ground around the pathway and main entrance.	Wheelchairs, walkers, and other mobility devices have difficulty moving over loose gravel. Surface can become uneven or muddy during wet weather, creating slipping or access hazards for students, staff, elders, and visitors with mobility challenges.	Remove or level existing gravel where required and install a paved surface leading to the main entrance to provide a stable, smooth, and accessible pathway.	Late Spring or Early Summer. Pending availability of the paving contractors.	School Administration / Facilities / Contractor